



“Lawn Art” Gets a Facelift

By Jon Usle

It has its own parking spot on our private street. It hadn't left its parking spot to go anywhere in six years due to a broken waterline for the kitchen faucet. The faucet waterline broke the last time we went camping. When the original converter

built the kitchen cabinets, they never left an access point to the faucet waterlines.

They left a viewing hole so you could see down there, but no access to the area. Seeing that this repair was way above my ability, I asked friends



Our 1957 PD 4104 is aptly named “Lawn Art”.


NATURE'S HEAD®

Self-Contained Composting Toilet
Saving Our Water for Tomorrow



FREE YOURSELF
From Black Tanks and Pumpouts.

- All Stainless Hardware
- Full Size Seat
- Fits in small places
- 5 Year Warranty
- No Chemicals
- Urine Diverting
- Exceptional Service
- Made in USA



www.NaturesHead.net
(251) 295-3043

